

# MEMORANDUM

DEPARTMENT OF TRANSPORTATION  
Staff Bridge Branch  
4201 E. Arkansas Avenue, Room 107  
Denver, Colorado 80222  
(303) 757-9309 FAX (303) 757-9197



Date: December 15, 2010

To: All Bridge Detail Manual Users

*Signature on File*

From: Mark A. Leonard, Bridge Branch Manager

Subject: CDOT Bridge Detail Manual Revisions

The following subsections of the CDOT Bridge Detail Manual have been updated or added:

Revision Log  
Table of Contents  
Chapter 16 – Repair Details

Chapter 16 has been added to provide minimum requirements and demonstrate current practices for structure repairs . These changes are available through the CDOT bridge web page.

<http://www.dot.state.co.us/Bridge/DetailManual/DetailManual.htm>

Please review and become familiar with these changes. If you have any questions or recommendations for improvement please contact:

[Thomas.Edwards@dot.state.co.us](mailto:Thomas.Edwards@dot.state.co.us) 757-9339  
[Mahmood.Hasan@dot.state.co.us](mailto:Mahmood.Hasan@dot.state.co.us) 757-9064

MAL/AJP/ajp

Distribution via e-mail:

Hutton	Program Engineers
McDaniel	Resident Engineers
Greer, FHWA	Staff Bridge Employees
Branch Managers	Structural Consultants